

ExteNet
Proposed DAS Nodes - Plandome Manor

Node ID	Lat.	Long	Village	Adjacent / Approximate Address	Sec Blk Lot	Existing Pole Height	Proposed Pole Height (w/ Antenna)	Pole Type	Antenna Location	Designed Antenna RAD Center Height (AGL)	Pole Owner	Existing Pole Line	Notes
15	40.81962893	-73.69764069	Plandome Manor	2 Aspen Gate Dr.	5 F 152	35	35	Existing wood pole	Comm Zone	24.25	PSEG	Y	
16	40.819172	-73.701937	Plandome Manor	1 Luquer Rd	5 F 121	34.75	34.75	Existing wood pole	Comm Zone	23.00	PSEG	Y	
18	40.817248	-73.701267	Plandome Manor	25 Morgan Court	5 F 151	N/A	36.33	New wood pole	Pole Top	35.33	ExteNet	Y	
19	40.816247	-73.703167	Plandome Manor	1526 Plandome Road	5 F 112	32.42	34	Replacement wood pole	Comm Zone	22.00	PSEG	Y	
20	40.81523828	-73.70043462	Plandome Manor	14 Rock Hollow Road	5 137 39	N/A	36.33	New wood pole	Pole Top	35.33	ExteNet	Y	
21	40.81609169	-73.69793559	Plandome Manor	21 Rock Hollow Road	5 135 22	29.5	29.5	Replacement wood pole	Comm Zone	21.75	PSEG	Y	Existing pole to be moved into ROW and replaced
22	40.813978°	-73.703749°	Plandome Manor	1 Water Ln	5 137 25	25.17	40.57	Replacement wood pole	Pole Top	39.57	PSEG	Y	
23	40.813864°	-73.696836°	Plandome Manor	54 Papermill Rd	5 136 9	N/A	34	New wood pole	Comm Zone	23.00	PSEG	Y	Existing pole is too far into property to move into ROW. Existing pole has transformer. New pole required.
24	40.814430°	-73.698093°	Plandome Manor	90 Gristmill Ln	5 137 42	N/A	34	Replacement wood pole	Comm Zone	23.50	PSEG	Y	Existing pole to be moved into ROW and replaced
26	40.81305697	-73.70683571	Plandome Manor	20 Andover Court	3 182 90	26.33	29.5	Replacement wood pole	Comm Zone	22.75	Verizon	Y	
27	40.81183499	-73.69774415	Plandome Manor	7 Papermill Road	5 135 3	25.57	29.5	Replacement wood light pole	Comm Zone	21.25	PSEG	Y	
28	40.812671	-73.690266	Plandome Manor	189 Circle Drive	5 152 97	30	36.33	Replacement wood pole	Pole Top	35.33	PSEG	Y	
29	40.81194305	-73.69279549	Plandome Manor	134 Circle Drive	5 125 1	30.24	30.24	Existing wood pole light pole	Pole Top	23.28	Verizon	Y	
30	40.812785°	-73.702787°	Plandome Manor	1405 Plandome Rd	3 182 72	N/A	40.57	New wood pole	Pole Top	39.57	PSEG	Y	Existing pole is too far into property to move into ROW. New pole required.
31	40.819823°	-73.700022°	Plandome Manor	8 Luquer Rd	5 072 670	N/A	30	New Ornamental Structure	Pole Top	29.00	ExteNet	N	No above ground infrastructure
33	40.81157252	-73.7015841	Plandome Manor	1 Stonytown Road	5 137 21	37.58	37.58	Existing wood pole	Comm Zone	23.50	PSEG	Y	
35	40.81177659	-73.69430307	Plandome Manor	100 Circle Drive	5 027 6	31.08	36.3	Replacement wood pole	Pole Top	35.33	PSEG	Y	
37	40.81049437	-73.6984965	Plandome Manor	2 Grist Mill Lane	5 137 28	24.25	36.33	Replacement wood pole	Pole Top	35.33	Verizon	Y	
39	40.8102834	-73.69113842	Plandome Manor	305 Circle Drive	5 152 77	25	36.33	Replacement wood pole	Pole Top	35.33	PSEG	y	
40	40.81059753	-73.70458305	Plandome Manor	1270 Plandome Road	3 009 17	24.58	36.33	Replacement wood light pole	Pole Top	35.33	PSEG	Y	

Updated June 27, 2019